





A collection of common tools: a spirit level, a pencil, a claw hammer, a Phillips screwdriver, a cordless drill, a tape measure, and a flathead screwdriver. To the right of the tools are two circular icons: one with a plus sign (+) and one with a minus sign (-).





WOOD DRILL $\varnothing 5\text{mm}$















4




5



6



7



8

