
























A	B	C (mm)			D
1	L99-1014	2000	300	22	2/3
2	L99-1015	2000	300	22	2/3
3	L99-4005	250	100	15	2/3
4	L99-4030	1450	950	36	1/3
5	L99-4031	1446	304	22	1/3
6	L99-4032	1400	261	18	1/3
7	L99-5005	1450	410	76	3/3
8	ZZ1-462	262	70	27	2/3
9	ZZ1-465	32	70	27	2/3
10	ZZ1-718	1995	70	27	2/3
11	ZZ1-747	1880	25	25	2/3








1h





D
2/3

1 §2



2x (11)



12x
Ø6,3x16 mm
e7


14x
Ø8x30 mm
f1

6x
Ø20x3mm
k103



2x
130x34x34/2 mm
n63

4x
Ø15x12 mm #16
r1

8x
20/11
r42

2 §6


4x
Ø15x12 mm #16 **r1**


3 §6





4x
Ø7x50 mm **e1**

4x
Ø6,3x16 mm **e7**




4x
M6x84 mm **j117**

4x
Ø10x16 mm **r43**




1x
4 mm **z1**













4A 



5A 



4B §6**5B** §6

6 

6x 
Ø4x35 mm p6

7