


































A	B	C (mm)			D
1	L99-1014	2000	300	22	2/4
2	L99-1015	2000	300	22	2/4
3	L99-4002	1646	304	22	1/4
4	L99-4005	250	100	15	2/4
5	L99-4007	1732	261	18	2/4
6	L99-4009	145	100	15	2/4
7	L99-4020	1650	950	36	1/4
8	L99-4027	1600	261	18	1/4
9	L99-5001	1650	410	76	4/4
10	L99-9006	1730	636	6	3/4

















1h



D
2/4

1 §2 §6










2 §6

 8x
 Ø15x12 mm #16 **r1**

3 §6

 4x
 Ø7x50 mm **e1**




 4x
 Ø6,3x16 mm **e7**

 4x
 M6x84 mm **j117**

 4x
 Ø10x16 mm **r43**

 1x
 4 mm **z1**


4 §6**5** §6

6 **7**