



































1h








A	B	C (mm)			D
1	L99-1014	2000	300	22	3/4
2	L99-1015	2000	300	22	3/4
3	L99-4005	250	100	15	3/4
4	L99-4016	1846	304	22	2/4
5	L99-4028	1850	950	36	1/4
6	L99-4029	1800	261	18	2/4
7	L99-5004	1850	410	76	4/4
8	ZZ1-462	262	70	27	3/4
9	ZZ1-465	32	70	27	3/4
10	ZZ1-718	1995	70	27	3/4
11	ZZ1-747	1880	25	25	3/4



1 §2 §6










2 §6

 4x
 Ø15x12 mm #16 **r1**

3 §6

 4x
 Ø7x50 mm **e1**









 4x
 Ø6,3x16 mm **e7**



 4x
 M6x84 mm **j117**

 4x
 Ø10x16 mm **r43**

 1x
 4 mm **z1**


4A **5A** 

4B §6**5B** §6

6 

6x  **p6**
Ø4x35 mm

7