




































1h













A	B	C (mm)			D
1	L99-1014	2000	300	22	3/5
2	L99-1015	2000	300	22	3/5
3	L99-4005	250	100	15	3/5
4	L99-4007	1732	261	18	3/5
5	L99-4009	145	100	15	3/5
6	L99-4016	1846	304	22	2/5
7	L99-4028	1850	950	36	1/5
8	L99-4029	1800	261	18	2/5
9	L99-5004	1850	410	76	5/5
10	L99-9007	1730	736	6	4/5





D
3/5

1  



2 §6


8x
Ø15x12 mm #16 r1


3 §6



4x
Ø7x50 mm e1






4x
Ø6,3x16 mm e7




4x
M6x84 mm j117

4x
Ø10x16 mm r43

1x
4 mm z1



4 §6**5** §6

6 **7**